



The base ISO of the M11 is 60. This is the lowest ISO setting on the M11, which provides the highest image quality with the least amount of noise. The traditional film sensitivities of 100, 200, 400, even 800 are also popular. Beyond 3200/4000 ISO the quality may slightly degrade.

When the ISO dial is on **A**, the ISO is automatically chosen by the camera and can be upper limited to avoid